

Ebara A70W Repair Kit

1.



	Bearing
	4 pcs

2.



	Bearing
	4 pcs

3.



	Lock Washer
	8 pcs

4.



	O-ring set
	1 pc