

Ebara AA70W Repair Kit

1.                    		Bearing 2 pcs	2.                    		Bearing 2 pcs
3.                    		Bearing 2 pcs	4.                    		Bearing 2 pcs
5.                    		O-ring set 1 pc			